

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-047	Smoke	9/5/2008	ADS/TM	S13GG1003MH	Dry	Yes	941.61



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-047	Smoke	9/5/2008	ADS/TM	S13GG1003MH	Dry	Yes	941.61

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG1009G1	S13GG1009MH	S13GG1021MH	266.7083	8
S13GG1003G1	S13GG1003MH	S13GG1005MH	203.8984	8
S13GG1021G1	S13GG1021MH	S13GG1003MH	239.5478	8
S13II1020G1	S13II1020MH	S13GG1009MH	231.4516	8

Observations & Photos

No smoke was observed during this test.

